

# *VAN'S AIRCRAFT, INC.*

14401 Keil Road NE, Aurora, Oregon, USA 97002

PHONE 503-678-6545 • FAX 503-678-6560 • [www.vansaircraft.com](http://www.vansaircraft.com) • [info@vansaircraft.com](mailto:info@vansaircraft.com)

Service Letters and Bulletins: <http://www.vansaircraft.com/public/notices.htm>

---

October 15, 2009

## Part Numbers:

EA DYNA VI I(O)-540	All 540 engines on RV-10
EA DYNA VI-STD	All Dynafocal 320/360 engines

The manufacturer of the Dynafocal vibration isolators sold by Van's and included in our firewall forward kits is unable to deliver these at present. We are endeavoring to find an alternate source, or different brand of isolators.

It is probable that the price of these mounts will increase when we do get them in. For those who have these parts back ordered from the firewall forward kits, we ask that you let us know whether you wish to have the isolators sent when we have them available (at a probable increased cost). Or if you wish to cancel the back order and source the mounts elsewhere.

If we do not receive a response we will assume that you wish us to ship the mounts and charge you when we have them available.

Equivalent part numbers for these mounts are:

EA DYNA VI STD	Lord	J 9613-49
	Barry Controls	94011-20
EA DYNA VI I(O)-540	Lord	J 3804-20
	Barry Controls	94110-01