



Max brightness on the dimmer is 12.3v

At dimmed value (4.7v), the engine analyzer LEDs were not illuminated.

Engine analyzer alarm is alternating (flashing). Difficult to get an accurate reading.

Component spec's:
LED: 2.2v, 20ma
Series Resistor: 390Ω

Parallel Resistor: 1kΩ