



2945 Bell Road #150 Auburn, CA 95603
 虎 (530) 613-6488

Annual Inspection & Repair Checklist

N Number [REDACTED]
 Tach 1992.8
 Date Jul 28, 2015
 Airplane's Birthday 06/07/1978

Aircraft make Grumman-American	AA5B Tiger	AA5B-0820	3413.80	1992.80
	Model	Serial Number	TT	TACH
Powerplant Lycoming	O360-A4K	24935-36A	3413.80	1992.80
	Model	Serial Number	TT	SMOH
Propeller Sensenich	76EM8S-10-0-63	33734K	1751.30	228.76
	Model	Serial Number	TT	SPOH

Date of Annuals and Aircraft Component Times

1. Date: Annual Inspection/Repair		02/18/11	02/15/12	02/15/13	04/10/14	05/08/15
2. Tachometer Time		1610.10	1656.50	1764.04	1901.10	1992.80
3. Airframe Total Time		3031.10	3077.50	3185.04	3322.10	3413.80
4. Engine Total Time since New		3031.10	3077.50	3185.04	3322.10	3413.80
5. Engine Total Time Since Major Overhaul	TBO: 2000 hrs	1610.10	1656.50	1764.04	1901.10	1992.80
6. Engine Total Time Since Top Overhaul	each 1000 hrs	1610.10	1656.50	1764.04	1901.10	1992.80
7. Propeller Total Time Since New		1368.60	1415.00	1522.54	1659.60	1751.30
8. Propeller Total Time Since Overhaul	each 1000 hrs	1368.60	1415.00	0.00	137.06	228.76
9. Left Mag (a):	PN: 4371 SN: 02090103	759.60	806.00	0.00	137.06	228.76
10. Right Mag (a):	PN: 4370 SN: 14071244	826.10	872.50	0.00	137.06	32.30
11. Vacuum Pump (b):	PN: 215CC SN: A55965	510.30	556.70	664.24	801.30	63.10
12. Alternator:	PN: AL12-F60 SN: 2F-71418	217.10	263.50	371.04	508.10	599.80
13. Starter:	PN: 149-12LS SN: F2L-610008	1162.90	1209.30	1316.84	1453.90	1545.60
14. Mech Fuel Pump:	PN: LW-16335-T SN: 63359407	624.70	671.10	778.64	915.70	1007.40
15. Elec Fuel Pump:	PN: 401126-1 SN:	3031.10	3077.50	3185.04	3322.10	3413.80
16. Carburetor/Injector:	PN: 10-5092 SN: CH-10-165	1610.10	1656.50	1764.04	1901.10	1992.80

1. ELT Battery	Make/Model: Narco ELT-10	Date	04/12	04/14	04/14	07/2016	07/2016
2. Transponder (c):	PN: AT-150 SN: 13685		04/11/08	09/01/11	09/01/11	04/12	05/2016
3. Altimeter/Static (d):	required for IFR flight		04/06	04/06	04/06	04/12	05/2016
4. Aileron AD (AD 79-22-04)	Alternate Means of Compliance		122.40	168.80	0.00	137.06	228.76
5. Vacuum Regulator Filter:	PN: RAB3-5-1 each 200 hrs / 2 years		57.90	0.00	107.54	0.00	91.70
6. Vacuum Inlet Filter:	PN: D9-18-1 each 500 hrs		245.10	291.50	399.04	0.00	91.70
7. Fuel Selector Valve:	each 500 hrs		245.10	291.50	399.04	536.10	627.80
8. Left Brakes:	PN: 066-00105		122.40	168.80	276.34	0.00	91.70
9. Right Brakes:	PN: 066-00105		122.40	168.80	276.34	0.00	91.70
10. Rudder Springs:	PN: 601053-2 each 1000 hrs		245.10	291.50	399.04	536.10	627.80

Flight time between inspections: 57.90 46.40 107.54 137.06 91.70

Notes

(a) recommended overhaul at 500 hours (c) each 24 mos. FAR 43.11 [91.413 (a)]
 (b) Recommended replacement at 600 hours (d) each 24 mos. FAR 43.9 [91.411 (a)(1)]