




1) both mags off (engine killed)



2) crank with mags off (no start)



3) crank with a hot mag (start!)



4) both mags on (engine running)

