

EAA TECHNICAL COUNSELOR VISIT REPORT

Visit: Initial Recurrent Final Date of Inspection: 3/16/2005

For Builder to complete

Name: STEVE DARTON EAA# 0418065 Chapter# 23

Address: 1273 STARWOOD CIR

City SANDY State UTAH Zip Code 84094

Email Address: SDARTON@YAHOO.COM Telephone: 801 971-1009

If you are willing to share your homebuilding experiences with other EAA members, about your project, please check how you would prefer to be contacted: Email Phone Letter

A/C Model: RV-10

Aircraft Registration "N" Number: _____ First Project NO YES (circle one)

NOTE: The EAA Technical Counselor is a volunteer technical advisor only and in this capacity has no authority to approve or "sign off" the aircraft or any aspect of their construction.

The EAA Technical Counselor Program is intended solely to facilitate informal contacts between homebuilders of aircraft and interested persons who have informed the Experimental Aircraft Association and/or its Chapters that they are available to render advice to such homebuilders. The EAA Technical Counselor is not an employee nor agent of the Experimental Aircraft Association or its Chapters.

Neither the Association nor its Chapters make any representation as to the Counselor's experience or competence with respect to aircraft building or restoration.

The builder agrees that he/she has read and understands the preceding, and consents to the distribution of this report to EAA Headquarters.

Signature of Builder(s): Steve Darton

Technical Counselor Visit/Activity Comments

Name: Glen Olsen EAA# 0352732 Chapter# 23 TC# 3366

Current Address: 7536 So. 2300 E. City Salt Lake City St Ut Zip 84121

Visit Comments/Activity Information

Great riveting job - Good Clean Work.

Excellent Workmanship!

(aft fuselage & empennage)