

Name	Country	Reg	Type	Hours	Landing sfc.	Mod 73 progress	Disbonding of TP6	Pip Pins	Problems found
Richard Iddon	UK	G-RIXS	Tri gear	365	Tarmac	Completed	None found	2in.	nothing major
Steve Pitt	UK	G-SMDH	Tri gear			Completed	None found	2in.	nothing major
Ron Jones	UK	G-RJWX	Mono			Completed	None found	Original	
Tim Ward	NZ	ZK-TIM	Mono			Not done	None found	Original	Very slight movement in starboard TP12. Present on installing (1998)- no worse
Danny Shepherd	UK	G-CERI	Tri Gear			Completed	None found	2in.	
Pete Jeffers	UK	G-BVIZ	Tri Gear			Completed	None found	2in.	well within limits
Brian Davies	UK	G-DDBD	Tri Gear			Completed	None found	2in.	none
Graham Drake	UK	G-CCOV	Mono			Completed	None found	1.9in.	
Sarah Attubato	UK	G-BXDP	Mono			Completed	None found	2in.	These are new replacement tailplanes that had already been built
David Watts	UK	G-BXDY	Mono			Completed	None found	2in.	
Nigel Charles	UK	G-MIME	Mono			Completed	None found	2in.	nothing major
Trev Pond	UK	G-LINN	Tri Gear		Grass	Completed	None found	Original	none